

1579 WIRE PROBE SENSOR



To Order : Please specify the complete assembly, indicate the code letter or value for each option.

1579	Calibration	Junction	Lead Wire	LW	Termination
	1	2	3	4	5
		SE			

1. SENSOR CALIBRATION

- J Iron ® / Constantan ®
- K Chromel ® / Alumel ®
- T Copper ® / Constantan ®

2. SENSOR JUNCTION

- SE Simplex, Exposed

3. LEAD WIRE

- LW4 AWG24, Stranded, FG-SSOB
- LW6 AWG24, Solid, FG-FG
- LW7 AWG24, Solid, PFA-PFA®
- LW8 AWG28, Solid, PFA-PFA®
- LW10 AWG30, PFA-PFA®
- LW11 AWG30, FG-FG

4. LW - LEAD LENGTH

- eg - 1000mm

5. TERMINATION

- 0 None, with Spade Lugs
- 2MP 2-Pin Miniature Plug
- 2MS 2-Pin Miniature Socket

